

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problems Mailbox.**

FIG. 1




FIG. 2






FIG. 3





5614




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG.13




FIG. 14




FIG. 15




FIG. 16




FIG. 16

FIG.17A




FIG.17C




FIG.17E




FIG. 17B




FIG.17D




FIG. 17F




FIG. 18




FIG. 19






FIG. 20



FOZ240-20F44860

FIG. 21



F1G.22B




FIG. 22A




FIG. 23




FIG. 24




FIG. 24

FIG. 25




FIG. 26




FIG. 27A




FIG. 27B




FIG. 27C




FIG. 28






FIG. 29



SET LIGHTNESS
OF ENTIRE SCREEN
TO 80%



DRAW EACH
THUMBNAİL
OVER

FIG. 30




FIG. 31




FIG. 32




FIG. 33






FIG. 34



TO 4240-2 OF 4860

FIG. 36



SECRET




FIG. 40




FIG. 41




FIG. 42




FIG. 43




FIG. 44




FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53




FIG. 54




FIG. 55





FIG. 56



TO2240" 20F44860

FIG. 57




FIG. 58




FIG. 59





FIG. 60



09844107-042701

FIG. 61






FIG. 62



09644107-042701

FIG. 63



09444107.042701

0944107.042704

FIG. 64




FIG. 65






FIG. 66




0944107 042701

FIG. 67




0944107 042701

FIG. 68



09844107-042701

FIG. 69



0944107.042701

FIG. 70





FIG. 70

FIG. 71



09844107-042701